





NOTES

1. 3 wire 115/230 volt single phase four (4) jaw socket permitted for services of 60 amps or less. Five (5) jaw socket required for services greater than 60 amps. Fifth jaw not used, but may be required if load increases a demand meter has to be fitted. Fifth jaw should always be connected to neutral.
2. A five jaw socket is always required for a 3 wire 115/200 volt network service.
3. Wiring should be installed so as not to obstruct meter plugs.



METER SOCKET WIRING
(3 WIRE SERVICE)

FIG 19